

**SAFETY AUDIT FORM – FEEDBACK ON AUDIT REPORT**

Received: 19/05/23

Scheme: Dunlo Hill , Ballinasloe  
 Stage: 1&2 Road Safety Audit  
 Date Audit (Site Visit) Completed: 29-3-2023

Paragraph No. in Safety Audit Report	Problem accepted (yes/no)	Recommended measure accepted (yes/no)	Alternative measures (describe)	Alternative measures accepted by Auditors (Yes/No)
3.1	yes	✓		
3.2	✓	✓		
3.3	yes	✓		

Signed.....*[Signature]*.....  
 Design Team Leader

Date.....5/5/23

Signed.....*[Signature]*.....  
 Audit Team Leader

Date.....5-5-2023.....

Signed.....*[Signature]*.....  
 Employer/Developer

Date.....05-05-23