

Outline Delivery Plan St. Paul's Secondary School

Oughterard,

Co. Galway

H91 PT86

Roll Number: 63101K





Purpose of Outline Delivery Plan

This Outline Delivery Plan contains concept designs of interventions improve infrastructure outside and on the routes to school with the aim of increasing the number of children who walk, cycle or scoot to school. These proposed interventions are based on survey findings, audits, consultation with the school and the Local Authority, and have been reviewed by the NTA and have been developed by the Safe Routes to School Officer.

The proposed interventions will require further work including detailed design, and input from stakeholders such as landowners and the local community. Some interventions may require planning permission. It is important to note that concepts and agreed solutions may not progress at the same time and some concepts may not be suitable, however all parties aim to work together to improve infrastructure in and around schools.

There is currently funding available to Local Authorities from the NTA to progress works arising from the Safe Routes to School programme.

Prepared for: Galway County Council

Prepared by: Safe Routes to School

Reviewed by: National Transport Authority

Date: November 2022



ST PAUL'S SECONDARY SCHOOL

School Summary

- St. Paul's Secondary School is located on the outskirts of Oughterard Village on Carrowmanagh Road.
- The school is a mixed secondary school that has approximately 437 students who attend the school daily. School starts at 9:00 am & finishes at 3:50 pm Monday & Tuesdays & 3:10pm on Wednesday, Thursday & Fridays.
- Staff parking occurs within the school grounds, along the front of the school and to the road adjacent to the school. All parking to the front of school is generally occupied by staff.
- Set-down occurs informally at the front of the school & on surrounding streets.
- Bus set down occurs on surrounding streets and on the roundabout immediately south of the school.

Key Audit Findings

- The speed limit outside the school is: Fixed 50km/h.
- High levels of congestion & dangerous parking/idling at on the road at the front of school & on the roundabout during school drop-off & collection.
- Scope to develop cycle/ pedestrian entrances to the school.
- Potential to establish Park'N'Stride at Rugby Grounds & Church (located at ≤ 500m from the school).
- The road bridge on the N59 crossing the Owenriff River is very narrow & has no
 provision for pedestrian & cycle crossing. This connection is critical to creating safe
 access from the school to Oughterard Village.
- Paths throughout Oughterard need improvement due to path obstructions &
 discontinuous nature of paths. Junctions are generally wide and the priority of
 pedestrians across junctions needs to be improved. Scope for new & improved
 paths & permeability links.

Supplementary information

- Oughterards Primary School, Scoil Chuimín & Caitríona is located across the road from St. Paul's Secondary School.
- TII has offered to fund for improvements to the road bridge on the N59 crossing the Owenriff River, however, this has not been progressed to date. Some of the ideas considered include:
 - A dedicated pedestrian & cycle bridge across the river.
 - A shuttle system for vehicles crossing the bridge with a path adjacent to the single lane of traffic.

Current Front of School Environment














Key Survey Findings

The school distributed the SRTS Parents Survey to all families of St Paul's Secondary School, Oughterard.

There was a 34.6%* response rate to the survey.


- 93.4% of parents surveyed agreed that road safety is a problem around the school
- 94.3% of parents would support works at the front of school that improve student safety, putting pedestrians and cyclists first
- 100.0% of parents would support works that would improve the walking and cycling links to school

Parents selected the following, when asked what improvements would support them walking, cycling or scooting to school:



Where students are travelling from


22.5% of students surveyed travel a distance of less than 1km to sepool.




- **School Location**
- High density of students travelling from this area
- Low density of students travelling from this area
- 1km distance from School
- 2km distance from School

How students are travelling to school


School bus is the dominant mode of transport for students traveling to school: 47.7% of students who completed the survey travel to school by school bus. Within a 2km radius of the school, car is the dominant mode for students traveling to school: 70.6% of these students drive to school. Within a 1km radius of the school, walking the dominant mode for students traveling to school: 58.8% of these students walk to school. Highlighting the need for improved pedestrian facilities and Park'N'Stride facilities.



How students within a 2km radius (48) are travelling to school




How students within a 1km radius (34) are travelling to school



Front of School Improvements

The focus of the front of school works is to create a safer front of school area by reducing congestion at the school gate by developing Park'N'Stride locations for the school. Access to the school for students walking & cycling can also be made safer through improved links connecting the school across the Owenriff River, to Oranmore Village & Park'N'Stride locations. The inclusion of a school signage will improve the overall visibility of the school.



a. School Zone

- 1. Antiskid road markings (SZ-116).
- The length of the school zone will require a curbed footpath on the side of the school protected by bollards (SZ-109).
- 3. One staff car parking space will need to be removed to facilitate new pedestrian & cycle entrance gate.

b. School Zone Gateway

- 1. At northern gateway: Raised table (SZ-123), road markings, school zone banners (SZ-133) & colored gateway totem (SZ-134).
- 2. At southern gateway: Pedestrian crossing (SZ-102) on raised table (SZ-123), road markings, school zone banners (SZ-133) & colored gateway totem (SZ-134).

ST PAUL'S SECONDARY SCHOOL

Front of School Improvements

c. Pedestrian Crossings

- 1. Controlled pedestrian crossing (SZ-103) on N59 at the Church.
- 2. Controlled pedestrian crossing (SZ-103) of Carrowmanagh Road near access to existing permeability link along Owenriff River.

d. Shared Space

 Road bridge on N59 is very narrow and there are no cycle or pedestrian facilities across the bridge. Ideally, a segregated pedestrian & cycle crossing is needed. The road remains too narrow for 2-way traffic. Suggest trailing a shuttle system and incorporating a single lane of traffic as well as walking & cycling shared space across the bridge.

e. Walking Links

 Section of footpath (SZ-126) is needed along Carrowmanagh Road connecting the bridge crossing towards the school.

f. Permeability Link

 Consider permeability link connecting Rugby Club to the back of the school.

g. New Entrances

 Consider 2 new combined pedestrian & cycle entrances to avoid pedestrians & cyclists having to use vehicular entrances: one at the front of the school & one to the rear.

h. Junction Tightening

- Consider tightening the roundabout outside the school to prevent illegal parking on the roundabout. Footpaths surrounding the roundabout should include pencil bollards (SZ-109) along the path edge to prevent cars from mounting the curbs.
- 2. Carrowmanagh Road / Abhainn Na Coille:
 - Junction tightening & entry treatment on Abhainn Na Coille (SZ-105).

3. N59 / Station Rd.:

 Junction tightening & entry treatment on Station Rd. (SZ-105).

i. Signposting

1. Signposting to be included both north & south of the school zone area as a forewarning of the presence of the school.

j. Park'N'Stride

- Park'N'Stride option at Oughterard Rugby
 Club (at 200m from school via permeability link
 & at 550m from school along the road).
- Park'N'Stride option at Church(at 500m from school).

k. Placemaking

 Scope for use of street art (SZ-139) & street furniture (SZ-132) in existing green space directly south of the school.

I. SuDS

1. Scope for use of SuDS via rain garden (SZ-135) /low-level planting (SZ-136), in existing green space directly south of the school.

ST PAUL'S SECONDARY SCHOOL

Elements of Proposed Scheme



Cold applied high friction buff surface



Raised totale



Colour themed signage



School branding banner / totem



Raised pedestrian crossing



Road Markings



Shared Space



Low level shrub planting




Colour themed street furniture



Micro art in footpath

Routes to School Improvements

The focus along routes to school is primarily focused on improving the walkability to the school through the improvement of footpaths, permeability links, narrowing of junctions & giving periestrians higher priority across junctions.



a. School Zone

1. As detailed in the section on Front of School Improvements above.

b. Walking Links

- 1. Improvement to existing footpaths east of Oughterard by the continuation of the path across junctions:
 - Entrance to Lemon Field
 - Entrance to the public car park
 - Entrance to Pier Road
- Improvement to existing footpaths & new sections of the footpath (SZ-126) along Camp Street:
 - Close to the junction with N59 bollards are needed to eliminate parked cars from encroaching on path space.
 - Suggest reducing road width & widening footpaths along the westerly side of Camp Street.

c. Permeability Links

- Improvement access to & lighting along the existing permeability link along Owenriff River from Glann Rd. to Carrowmanagh.
- Improvement access to & surface along the existing permeability link connecting Cregg View to Clifden Road via the grounds of Oughterard Courthouse.

d. Junction Tightening

- 1. N 59 / Camp St.:
 - Junction tightening & entry treatment on Camp St. (SZ-105).
- 2. Camp St. / Glann Rd.:
 - Junction tightening & entry treatment on Glann Rd. (SZ-105). Opportunity to narrow carriageway width and widen footpaths along westerly side of Camp Street / Southerly side of the Glann Road.

e. Park'N'Stride

1. Park'N'Stride option at Oughterard Rugby Club and at Church as detailed in item j. of the front of school improvement above.

Received: 21/07/2023

Appendix A Parent Survey Results



Safe Routes to School Parent Survey Questions

Q1. How many of your children attend this school?

Select a number (from 1 – 8) from a drop down

Received. 27/07/20 **Q2.** Where does the journey to school begin? (Parents selected a location on a map)

· To help improve routes to school, we want to get an idea of the locations from where students are travelling to school. Please indicate where your school journey begins on the map. It does not have to be directly on your home. It can be a point nearby, such as your estate entrance.

Q3. For each child, choose their gender:

Select Male, Female or Prefer not to say

Q4. For each child, choose their class:

- Primary: Junior Infants, Senior Infants, 1st Class, 2nd Class, 3rd Class, 4th Class, 5th Class, 6th Class
- Secondary: 1st Year, 2nd Year, 3rd Year, 4th Year, 5th Year, 6th Year

Q5. For each child, choose how they usually travel to school:

Walk, Cycle, Scoot, Park 'n' Stride, Car, School Bus, Public Transport

Q6. Do you think road safety is a problem around your school?

Select either Yes or No.

Q7. Would you support works at the front of school that improve student safety, putting pedestrians and cyclists first?

• Select either Yes or No

Q8. Would you support works that improve the walking and cycling routes to your school?

Select either Yes or No

Q9. What improvements would support you to walk, cycle or scoot to school?

■ New	or im	nroved	foot	naths
	OI 11 1	1010104	1001	panis

- New or improved cycle paths
- Safer crossing points
- ☐ Reduced traffic speed
- ☐ Fewer cars at the school gate
- □ Cycle parking at the school
- □ Other
- None of these

Comments box (optional) up to 500 characters.


ST PAUL'S SURVEY RESULTS

The school distributed the SRTS Parents Survey to all families of St Paul's Secondary School, Oughterard via their usual communications methods, during October 2021. Reminders were also 106 151 = 34.6% of school population (based on a total of 437)* issued.


Responses received:

Students represented:

Q1. How many of your children attend this school?




Q2. For each child, choose their gender







Q4. For each child, choose how they usually travel to school




Q5. Do you think road safety is a problem around your school?



Q6. Would you support works at the front of school that improve student safety, putting pedestrians and cyclists first?




Q7. Would you support works that improve the walking and cycling routes to your school?





Parent Comments



34 parent comments were received in total and have been categorised in the chart. Each comment was placed in the [one] category most applicable, even if there was crossover into another category.

Received: 21/07/2023

Appendix B Audit Report



Overview

The following Audit Report captures the existing conditions of the front of school environment of St. Paul's Secondary School and specified routes within 1km of the school.

The SRTS Infrastructure Officer conducted the audit to assess the safety and accessibility of the front of school and opportunities to facilitate active travel on routes to school.

A separate GIS analysis of where students started their journey to school identified the primary routes to school.

Findings from the audit support the key recommendations outlined in the delivery plan for the school.

Prepared for: Galway County Council

Date: January 2022

Prepared by: Safe Routes to School




ST. PAUL'S AUDIT REPORT

Findings at the Front of School

Front of School Area





Area audited along front of school for St. Paul's Secondary School

Front of School Findings

Item ID: FOS-4846

Item Category: Junctions and Crossings - No tactile paving or dropped curb

Notes: narrowing of junction and continuation of path across entrance Abhainn

Na Coille.





Location: www.google.com/maps/place/53.4290826,-9.326194

Item ID: FOS-4847

Item Category: Junctions and Crossings - Formal crossing needed

Notes: formal crossing needed at this location





Location: www.google.com/maps/place/53.4300566,-9.3274283

Item ID: FOS-4848

Item Category: Opportunities - School zone

Notes: scope for school zone in this area



Received: 27/07/2023

Location: www.google.com/maps/place/53.430758172532364,-9.328144733796822

Item ID: FOS-4849

Item Category: Opportunities - Permeability link

Notes: there may be potential to create a pedestrian & cycle entrance to the school at this location so as to avoid entering at the vehicular entrance.



Location: www.google.com/maps/place/53.43021258607831,-9.327622249468478

Item ID: FOS-4850

Item Category: Opportunities - School zone

Notes:





Location: www.google.com/maps/place/53.4299175,-9.327095

Item ID: FOS-4851

Item Category: Opportunities - Permeability link

Notes: Potential to create a permeability link connecting Rugby Grounds (which could be used as a park'N'Stride location to Carrowmanagh to the rear of the school.



Location: www.google.com/maps/place/53.4288467,-9.3291082

Item ID: U-4852

Item Category: Opportunities - Park and Stride

Notes: Potential to create a Park'N'Stride at this location in order to remove

congestion and informal set down from the front of the school.



Location: www.google.com/maps/place/53.4290556,-9.3293135

Item ID: U-4855

Item Category: Opportunities - Permeability link

Notes: Potential to create a permeability link connecting Rugby Grounds (which could be used as a Park'N'Stride location to Carrowmanagh to the rear of the school.








Location: www.google.com/maps/place/53.4284947,-9.329399

ST. PAUL'S AUDIT REPORT

Findings on the Routes to School

Map of Routes Audited





Routes audited for St. Paul's Secondary School

Route A: East of village from graveyard Pier Road Camp Street Findings

Item ID: A-4825

Item Category: Roads and Surfaces - Speed limit

Notes: Transition from 100 to 60 footpath but no hard shoulder. Footpaths are narrow.





Location: www.google.com/maps/place/53.4245232,-9.3099225

Item ID: A-4826

Item Category: Roads and Surfaces - Uneven surface or potholes

Notes: Entrance to lemon field. Road maintenance needed.





Location: www.google.com/maps/place/53.4258856,-9.3131736

Item ID: A-4827

Item Category: Roads and Surfaces - Road width

Notes: Road & footpaths are narrow.





Location: www.google.com/maps/place/53.4266442,-9.3152342

Item ID: A-4828

Item Category: Footpaths and Verges - Footpath too narrow

Notes: footpaths are very narrow.





Location: www.google.com/maps/place/53.4274282,-9.3166237

Item ID: A-4829

Item Category: Opportunities - Park and Stride

Notes: Public Car Park potential Park'N'Stride location at 1km from school.





Location: www.google.com/maps/place/53.4278157,-9.3171559

Item ID: A-4833

Item Category: Junctions and Crossings - Continuous footpath needed

Notes: crossing/continuation of footpath across entrance to car park is needed





Location: www.google.com/maps/place/53.4279286,-9.317334

Item ID: A-4830

Item Category: Footpaths and Verges - No footpath

Notes: Footpaths to not continue along Pier Road.





Location: www.google.com/maps/place/53.429163,-9.3167034

Item ID: A-4831

Item Category: Footpaths and Verges - Discontinued footpaths

Notes: Footpaths are discontinued at this location along Pier Road



Location: www.google.com/maps/place/53.4284077,-9.317397

Item ID: A-4832

Item Category: Junctions and Crossings - Formal crossing needed

Notes: crossing/ continuation of footpath across Pier road is needes





Location: www.google.com/maps/place/53.4281575,-9.3177009

Item ID: A-4834

Item Category: Opportunities - Street furniture

Notes: Opportunity for placemaking/street furniture/rain garden at this location

(1km from school).





Location: www.google.com/maps/place/53.4282469,-9.3178304

Item ID: A-4835

Item Category: Junctions and Crossings - Junction layout

Notes: Tightening of junction on to Camp Street is needed and entry treatments.

Elimination of cars parking on the bends at this location is also needed









Location: www.google.com/maps/place/53.428746,-9.3193824

Item ID: A-4836

Item Category: Footpaths and Verges - Obstructions / street furniture

Notes: Parked cars encroach on footpath space along Camp Street. Bollards


needed to protect footpath.





Location: www.google.com/maps/place/53.428609,-9.3195468

Item ID: A-4837



Location: www.google.com/maps/place/53.4293469,-9.3194892

Item ID: A-4838

Item Category: Roads and Surfaces - Road width

Notes: Footpath is not continuous along both sides of the road along Camp Street

but rather hops from one side to other





Location: www.google.com/maps/place/53.4300957,-9.3196669

Item ID: A-4839

Item Category: Footpaths and Verges - Obstructions / street functions

Notes: Obstructions blocking footpaths along Camp Street. This rouse is used by

students at break time





Location: www.google.com/maps/place/53.4309255,-9.3199448

Item ID: A-4840

Item Category: Footpaths and Verges - Footpath too narrow

Notes: footpaths are too narrow.





Location: www.google.com/maps/place/53.431912,-9.3201889

Item ID: A-4841

Item Category: Junctions and Crossings - Formal crossing needed

Notes: Suggest reducing road width and widening footpaths along this route along the westerly side of Camp Street/ Southerly side of the Glann Road.





Location: www.google.com/maps/place/53.4313451,-9.3201236

Item ID: A-4842

Item Category: Footpaths and Verges - Discontinued footpaths

Notes: In 80 kph zone plenty of road width for footpaths to be continued to junction





Location: www.google.com/maps/place/53.4328716,-9.3227695

Route B: Village + Station Road Findings

Item ID: B-4856

Item Category: Roads and Surfaces - Road width

Received. 27 Notes: Road bridge on N59 is very narrow and there are no cycle or pedestrian facilities across the bridge. Ideally a segregated pedestrian and cycle crossing is needed. The road remains too narrow for 2-way traffic. Suggest trailing a shuttle system and incorporating a single lane of traffic as well as a shared space/footpath across the bridge.





Location: www.google.com/maps/place/53.427404,-9.3270227

Item ID: B-4857

Item Category: Footpaths and Verges - Discontinued footpaths

Notes: Footpath is discontinued at this location along Station Rd.





Location: www.google.com/maps/place/53.4269054,-9.3267099

Item ID: B-4858

Item Category: Opportunities - Park and Stride

Notes: Opportunity for Park'N'Stride on the grounds of the Church (located at 500m from the school) – particularly for busses dropping and collecting from the schools. However, a safe pedestrian crossing of the Oweniff River is first required.



Location: www.google.com/maps/place/53.4269227,-9.3287466

Item ID: B-4859

Item Category: Junctions and Crossings - Junction width

Notes: Junction of Station road needs to be tightened and pedestrian facilities continued across the junction.





Location: www.google.com/maps/place/53.4273104,-9.3267759

SAFE ROUTES TO SCHOOL

Item ID: B-4860

Item Category: Footpaths and Verges - Discontinued footpaths

Notes: Footpaths discontinued at this location along Station Rd.





Location: www.google.com/maps/place/53.422468,-9.3285001

Item ID: B-4861

Item Category: Opportunities - Permeability link

Notes: Opportunity of permeability link connecting Cregg View to Clifden Road via grounds of Oughterard Courthouse.









Location: www.google.com/maps/place/53.4276571,-9.3249805

Item ID: B-4862

Item Category: Footpaths and Verges - Discontinued footpaths

Notes: footpaths within Cregg View are discontinued at this location





Location: www.google.com/maps/place/53.4275786,-9.3227483

Item ID: B-4863

Item Category: Footpaths and Verges - Discontinued footpaths

Notes: footpath discontinued at this location along Clifden Rd



Location: www.google.com/maps/place/53.4281677,-9.322238

SAFE ROUTES TO SCHOOL

Item ID: B-4864



Location: www.google.com/maps/place/53.4284069,-9.3207555

Route C: N59 + water's edge north of river Findings

Item ID: C-4843

Item Category: Accessibility - Abrupt level change

Received. Notes: Access to this existing permeability link from Glann Rd. to Carrownanagh along Owenriff River has an abrupt level change. This route also does not currently have lighting along the route.





Location: www.google.com/maps/place/53.4313742,-9.3210658

Item ID: C-4844

Item Category: Accessibility - Entrance/access too narrow

Notes: Access to this existing permeability link from Glann Rd. to Carrowmanagh

along Owenriff River is too narrow.



Location: www.google.com/maps/place/53.4283786,-9.3254359

Item ID: C-4845

Item Category: Junctions and Crossings - Continuous footpath Reeded

Notes: footpaths along Carrowmanagh are discontinuous and a continuous










Location: www.google.com/maps/place/53.4283254,-9.325466

Item ID: C-4853

Item Category: Footpaths and Verges - Discontinued footpaths

Notes: footpaths along Carrowmanagh are discontinuous and a continuous





Location: www.google.com/maps/place/53.4282493,-9.3256628

Item ID: C-4854

Item Category: Opportunities - Park and Stride

Notes: Opportunity for Park'N'Stride in rugby grounds (at 600m from school along main road & <300m from school via proposed permeability link from Rugby Grounds to Carrowmanagh.





Location: www.google.com/maps/place/53.4278494,-9.329006

Received. 27/07/2023

Appendix C Audit Summary



Audit Summary

School: St. Paul's Secondary School, Oughterard Co Galway, H91PT86

Prepared for: Galway County Council



Peceived. 27/07/2023

- School location
- Front of School
- Footpaths and Verges
- Roads and Surfaces
- Junctions and Crossings
- Signage and Road Markings
- Road User Behaviour
- Accessibility
- Cycle Infrastructure
- Opportunities
- 40 Items recorded

Item Category	Route	Item ID	Location Po
Footpaths and Verges - Obstructions / street furniture	East of the village from the graveyard, Pier Road & Camp Street	A-4836	www.google.com/maps/place/53.428609,-9.3195468
Footpaths and Verges - Obstructions / street furniture	East of the village from the graveyard, Pier Road & Camp Street	A-4839	www.google.com/maps/place/53.4309235,-9.3199448
Footpaths and Verges - No footpath	East of the village from the graveyard, Pier Road & Camp Street	A-4830	www.google.com/maps/place/53.429163,-9.3167034
Footpaths and Verges - Footpath too narrow	East of the village from the graveyard, Pier Road & Camp Street	A-4828	www.google.com/maps/place/53.4274282,-9.3166237
Footpaths and Verges - Footpath too narrow	East of the village from the graveyard, Pier Road & Camp Street	A-4840	www.google.com/maps/place/53.431912,-9.3201889
Footpaths and Verges - Discontinued footpaths	East of the village from the graveyard, Pier Road & Camp Street	A-4831	www.google.com/maps/place/53.4284077,-9.317397
Footpaths and Verges - Discontinued footpaths	East of the village from the graveyard, Pier Road & Camp Street	A-4837	www.google.com/maps/place/53.4293469,-9.3194892
Footpaths and Verges - Discontinued footpaths	East of the village from the graveyard, Pier Road & Camp Street	A-4842	www.google.com/maps/place/53.4328716,-9.3227695
Footpaths and Verges - Discontinued footpaths	N59 & waters edge north of the river	C-4853	www.google.com/maps/place/53.42814190502952,- 9.32577652572773

Item Category	Route	Item ID	Location 🍖
Footpaths and Verges - Discontinued footpaths	Village & Station Road	B-4857	www.google.com/maps/place/53.42687215763936,- 9.326701317062119
Footpaths and Verges - Discontinued footpaths	Village & Station Road	B-4860	www.google.com/maps/place/53.422468, 9.3285001
Footpaths and Verges - Discontinued footpaths	Village & Station Road	B-4862	www.google.com/maps/place/53.4275786,-9.3227483
Footpaths and Verges - Discontinued footpaths	Village & Station Road	B-4863	www.google.com/maps/place/53.4281677,-9.322238
Roads and Surfaces - Uneven surface or potholes	East of the village from the graveyard, Pier Road & Camp Street	A-4826	www.google.com/maps/place/53.4258856,-9.3131736
Roads and Surfaces - Speed limit	East of the village from the graveyard, Pier Road & Camp Street	A-4825	www.google.com/maps/place/53.4245232,-9.3099225
Roads and Surfaces - Road width	East of the village from the graveyard, Pier Road & Camp Street	A-4827	www.google.com/maps/place/53.4266442,-9.3152342
Roads and Surfaces - Road width	East of the village from the graveyard, Pier Road & Camp Street	A-4838	www.google.com/maps/place/53.4300957,-9.3196669
Roads and Surfaces - Road width	Village & Station Road	B-4856	www.google.com/maps/place/53.427492218867584,- 9.327057032242639

Item Category	Route	Item ID	Location
Junctions and Crossings - No tactile paving or dropped kerb	Front of School	FOS-4846	www.google.com/maps/place/83,4290826,-9.326194
Junctions and Crossings - Junction width	Village + Station Road	B-4859	www.google.com/maps/place/53.42740309899084,- 9.326519480883624
Junctions and Crossings - Junction layout	East of the village from the graveyard, Pier Road & Camp Street	A-4835	www.google.com/maps/place/53.428623264288994,- 9.319412440609998
Junctions and Crossings - Formal crossing needed	East of the village from the graveyard, Pier Road & Camp Street	A-4832	www.google.com/maps/place/53.4281575,-9.3177009
Junctions and Crossings - Formal crossing needed	East of the village from the graveyard, Pier Road & Camp Street	A-4841	www.google.com/maps/place/53.431265838002915,- 9.320157932078937
Junctions and Crossings - Formal crossing needed	Front of School	FOS-4847	www.google.com/maps/place/53.4300566,-9.3274283
Junctions and Crossings - Continuous footpath needed	East of the village from the graveyard, Pier Road & Camp Street	A-4833	www.google.com/maps/place/53.42780330482299,- 9.317213837232593
Junctions and Crossings - Continuous footpath needed	N59 & waters edge north of river	C-4845	www.google.com/maps/place/53.4283254,-9.325466

Item Category	Route	Item ID	Location
Accessibility - Entrance/access too narrow	N59 & waters edge north of river	C-4844	www.google.com/maps/place/53.42826289502335,- 9.325475596660667
Accessibility - Abrupt level change	N59 & waters edge north of river	C-4843	www.google.com/maps/place/53.431374239.3210658
Accessibility - Abrupt level change	Village & Station Road	B-4864	www.google.com/maps/place/53.4284069,-9.3207555
Opportunities - Street furniture	East of the village from the graveyard, Pier Road & Camp Street	A-4834	www.google.com/maps/place/53.4282469,-9.3178304
Opportunities - School zone	Front of School	FOS-4848	www.google.com/maps/place/53.430758172532364,- 9.328144733796822
Opportunities - School zone	Front of School	FOS-4850	www.google.com/maps/place/53.4299175,-9.327095
Opportunities - Permeability link	Front of School	FOS-4849	www.google.com/maps/place/53.43011030985638,- 9.327502086373642
Opportunities - Permeability link	Front of School	FOS-4851	www.google.com/maps/place/53.4288467,-9.3291082

Item Category	Route	Item ID	Location
Opportunities - Permeability link	Front of School	FOS-4855	www.google.com/maps/place/53.4284947,-9.329399
Opportunities - Permeability link	Village & Station Road	B-4861	www.google.com/maps/place/53.4276571,-9.3249805
Opportunities - Park and Stride	East of the village from the graveyard, Pier Road & Camp Street	A-4829	www.google.com/maps/place/53.42785405568253,- 9.31697565568518
Opportunities - Park and Stride	Front of School	FOS-4852	www.google.com/maps/place/53.4290556,-9.3293135
Opportunities - Park and Stride	N59 & waters edge north of river	C-4854	www.google.com/maps/place/53.42777013148408,- 9.329139037501644
Opportunities - Park and Stride	Village & Station Road	B-4858	www.google.com/maps/place/53.4269227,- 9.328746599999999

End of Document



